



1. Approving National Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking No.: 32826	
4. Organization Name and Address: New England Propeller Service, Inc. RC2R130L				P.O. Box 244 East Haddam, CT 06423-2388 (860) 873-1494 • Fax: (860) 873-2388		5. Work Order/Contract/Invoice Number: CR-32826	
6. Item:	7. Description:	8. Part Number:	9. Eligibility:	10. Quantity:	11. Serial/Batch Number:	12. Status Work:	
1	HARTZELL PROPELLER	BHC-C2YF-1BP F 8459A-8R	N/A	1	AM2559	REPAIRED	
13. Remarks: THIS COMPONENT WAS INSPECTED AND REPAIRED IN ACCORDANCE WITH MANUFACTURER'S MANUAL 113BR32, 202A (V1R30, V7R29, V8R28, V11R29) PROPELLER DISASSEMBLED, CLEANED AND VISUALLY INSPECTED FOR GREASE LEAK REPAIR. ALL SEALS REPLACED. PROPELLER ASSEMBLED, SET ANGLES, TRACKED, BALANCED AND GREASED. THIS WAS THE ONLY WORK PERFORMED.							
14. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13.				19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work the items are approved for return to service.			
15. Authorized Signature:		16. Approval/Authorization No.:		20. Authorized Signature: 		21. Approval/Certificate No.: RC2R130L	
17. Name (Typed or Printed):		18. Date (m/d/y):		22. Name (Typed or Printed): ARTIE D'ONOFRIO, PRESIDENT		23. Date (m/d/y): 9-14-06	
User/Installer Responsibilities							
It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

3. Form Tracking No.: 32826	
5. Work Order/Contract/Invoice Number: CR-32826	
11. Batch Number: AM2559	12. Status Work: REPAIRED
(VIR30, V7R29, V8R28, V11R29)	
UNED EASE CED. LES, SED. MED.	
Service <input type="checkbox"/> Other regulation specified in Block 13 wise specified in Block 13, the work identified in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, Part 43 and in respect to that work the items are approved	
	21. Approval/Certificate No.: RC2R130L
NOFRIO, PRESIDENT	23. Date (m/d/yy): 9-14-06
of the country specified in Block 1 it is essential that the user/installer ensures that the work was issued in accordance with the national regulations by the user/installer	

NSN: 0052-00-012-9005

PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model BHC-C2YF-1BF

Blade Design F8459A-8R

Diameter _____

Hub Ser. No. AM2559

Blade Ser. Nos.

No. 1 D 54049

No. 2 D 54037

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High 29.0 Low 17.4

Feather _____ Reverse _____

Governor Model _____

RIGHT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. No. _____

Blade Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

DESCRIPTION OF ALL OPERATIONS
 PERTAINING TO AIRWORTHINESS DIRECTIVES,
 SERVICE BULLETINS, SERVICE LETTERS,
 & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
9-14-06		BHC-C2YF-1BF / F8459A-8R	S/N AM 2559
		PROPELLER DISASSEMBLED, CLEANED AND VISUALLY INSPECTED FOR GREASE LEAK REPAIR. ALL SEALS REPLACED. PROPELLER ASSEMBLED, SET ANGLES, TRACKED, BALANCED AND GREASED. THIS WAS THE ONLY WORK PERFORMED	
		AUTHORIZED BY	<i>[Signature]</i> W/O # CR-32826
		FOR NEW ENGLAND PROPELLER SERVICE, INC. EAST HADDAM, CT FAA REPAIR STATION # RC2R130L 1-800-878-6377	<i>[Signature]</i> President

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
------	-----------	---------------------	-----------



— Date: 10/24/2007; Aircraft: N821ET; Type: PA28R-201T; S/N: 28R-7703147; Hobbs: 0 00; Tach: 3659 20; Total Time: 3649 82
 — * Inspected the propeller. Dressed each blade to remove minor nicks and abrasions Painted each blade face with flat black paint
 — Serviced the propeller with Aeroshell 6.

— I certify that this propeller has been inspected in accordance with an Annual/100 hour inspection and was determined to be in
 — airworthy condition and is approved for return to service Pertinent details of this inspection are on file at Infinity Aviation Services
 — LLC under the work order listed

— Signature: Lee Abt A&P IA 79504149
 — Date: 10/24/2007, W/O: 111824

Date:
* Inspe
Painte

I certifi
conditi
work o

Signat
Date:
Infinity
FAA C
#16FF

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
------	--------------	---------------------	-----------



Date: 12/15/2008; Aircraft: N821ET; Type: PA28R-201T; S/N: 28R-7703147; Hobbs:; Tach: 3764.61; Total Time: 3764.61
 * Inspected the propeller Dressed each blade to remove minor nicks and abrasions Painted each blade face with flat black paint
 Painted each blade tip matching the previous color as required

I certify that this propeller has been inspected in accordance with an Annual/100 hour Inspection and was determined to be in airworthy condition and is approved for return to service Pertinent details of this inspection are on file at Infinity Aviation Services LLC under the work order listed

Signature: Lee Abt

Date: 12/15/2008, W/O: 112445
 Infinity Aviation Services LLC
 FAA Certified Repair Station
 #16FR992Y

